

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Quana M. Grainger
	:	
Akira HIGETA, et al.)	Group Art Unit: 2852
	:	
Appln. No.: 09/695,868)	Patent No.: 7,062,199 B1
	:	
Filed: October 26, 2000)	Issued: June 13, 2006
	:	Confirmation No.: 3187
For: PROCESS CARTRIDGE)	
REMANUFACTURING METHOD	:	June 8, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The Commissioner is hereby authorized to charge Deposit Account No. 06-1205 for \$100.00 to cover the statutory fee for such Certificate of Correction. Please charge any required additional fee or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Daniel S. Glueck/
Attorney for Patentees
Daniel S. Glueck
Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200
DSG:eyw

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,062,199 B1

DATED : June 13, 2006

INVENTOR(S) : Akira Higeta, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE

At Item (57), Abstract, Line 1, "remanufacting" should read --remanufacturing--.

IN THE DRAWINGS:

Sheet 40, Figure 51, Item S8, "CLEANIG" should read --CLEANING--.

COLUMN 1:

Line 61, "remanufacting" should read --remanufacturing--.

COLUMN 2:

Line 35, "remanufact" should read --remanufactur--.

COLUMN 3:

Line 64, "remanufact" should read --remanufactur--.

COLUMN 5:

Line 58, "Jun. 27," should be deleted.

Line 59, "2005" should be deleted.

COLUMN 9:

Line 40, "fee" should read --free--.

COLUMN 10:

Line 57, "and portions" should read --end portions--.

COLUMN 13:

Line 23, "position" should read --positioned--.

COLUMN 14:

Line 55, "the," should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,062,199 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,062,199 B1

DATED : June 13, 2006

INVENTOR(S) : Akira Higeta, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 23, "12b6 P." should read --12b6.--.

Line 39, "blade 10e2." should read --metal blade 10e2.--.

COLUMN 23:

Line 44, "MI" should read --M1--.

COLUMN 24:

Line 30, "contract" should read --contact--.

COLUMN 25:

Line 24, "remanufacturing" should read --remanufacturing--.

Line 28, "sad" should be deleted.

COLUMN 26:

Line 28, "remanufacturing" should read --remanufacturing--.

COLUMN 27:

Line 15, "said" should be deleted.

Line 22, "seat" should read --seal--.

Line 63, "remanufacturing" should read --remanufacturing--.

COLUMN 28:

Line 31, "12a" should read --12a1--.

Line 56, "remanufacturing" should read --remanufacturing--.

COLUMN 29:

Line 63, "drum 1" should read --drum 7--.

Line 66, "drum 1" should read --drum 7--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,062,199 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,062,199 B1

DATED : June 13, 2006

INVENTOR(S) : Akira Higeta, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 3, "drum 1" should read --drum 7--.

Line 33, "tone" should read --toner--.

COLUMN 31:

Line 15, "flexible" should read --the flexible--.

COLUMN 32:

Line 12, "used a" should read --a used--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,062,199 B1

No. of add'l. copies
@ 30¢ per page

